

Under Review Notification

Raised By: VANESSA MOREL

Date: 19.07.18

Product #: Dart Tooling BELL

Product Name: M/R BLADE BOLD

EXTRACTOR

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	PP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
RBT18526	RBT18526 REV 1	Y	Y	N	Y	N	Y	N	19-820	SEE BELOW
RBT18526-1A	RBT18526 REV 1	Y	Y	N	Y	N	N	N	19-820	SEE BELOW

Description of Issue: RBT18526 : CUSTOMER ISSUE NCR19-7317

CUSTOMER COMMENTS : During the separation process of the bolt from the cube, the bolt became so hard and wearing the nut threads also damaged the pulley rod assy threads.
Now the tool and the pulley rod are both damaged

CUSTOMER WILL SEND THE TOOL BACK TO ENGINEERING FOR MORE INVESTIGATIONS

Distribution:

VP Operations

Director of Operations

Director Quality Assurance

QC Coordinator

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider

Supply Chain Director / Senior Buyer

Marketing Eugene